BUILDING CODE ADMINISTRATION PROGRAM 4202 E. FOWLER AVENUE, OPM 100 FACILITIES MANAGEMENT EDITION: OCTOBER 17, 2016

TAMPA, FLORIDA 33620-7550 WEBSITE: www.usf.edu/fm-ehs



Fax: (813) 974-2465 PHONE: (813) 974-0893 EMAIL: <u>roy1@usf.edu</u>

USF TAMPA HVAC REPLACEMENT REQUIREMENTS SUMMARY

BCA DIRECTIVE -- 09

INDEX	SECTIONS	TITLE
	SECTION A	Purpose
	SECTION B	REQUIREVENTS
	SECTION C	REFERENCE

PURPOSE: Α

This BCA Directive promulgates summary of code requirements for HVAC replacement equipment in 2014

809.3 Local exhaust. All newly introduced devices, equipment, or operations that produce airborne particulate matter, odors, fumes, vapor, combustion products, gaseous contaminants, pathogenic and allergenic organisms, and microbial contaminants in such quantities as to affect adversely or impair health or cause discomfort to occupants shall be provided with local exhaust.

811.1 Minimum requirements. Alterations subject to this Chapter shall comply with the requirements of the